

Application

Surface should be absolutely clean and dry. Product may not work on insufficient cleaned surfaces. Ventilate the application area well. Spray the product evenly onto the surface until the entire area becomes moist. Surfaces which do not absorb product should be spread with a cloth slightly. Wait for 24h for drying and curing period. Effect of product can change with respect to fabric type. Curing time is 24h at 23°C - 50% RH.

Specifications

Packaging	50 mL
Appearance	Colorless liquid
Durability	Up to 1 years
Chemical Resistance	11>pH>1
Dry Film Thickness	90-100 nm
Density @23°C	1.01 g/cm3
pH Value	4-5
Dry to Touch Time	6h
Application Temperature	+5°C to +45°C (≤50%RH)
Temperature Durability	150°C